Tube-Based Crossovers

January 2003, p. 60-65 (020297-1).

A number of errors have crept into the drawings in Figure 3 on page 61 of the article. In Figure 3a, two unnecessary and possibly harmful wire links are shown, while the labels '115 V' and '230 V' in Figures 3a and 3b should have been transposed. Also, all transformer secondaries should have been marked '115 V', not '15 V'. To prevent misunderstandings the corrected drawings are printed here.



020297- 13

Small DC-DC Converters

January 2003, p. 54-58 (020180-1).

In Figure 3, point 'P' (mentioned in the text) is not indicated. The relevant point is the junction of the collector of T1, choke L1, resistor R1, the cathode of diode D1 and the base of T2.